Work Order ID 56977 Tuesday, March 16, 2010 10:20:59 AM											Page
Revision ID:	D4035-047	nbly, Aft (Light)		Accept				 s	Setup St St	1 1301111	
	3/16/2010	Start Qty: 4.00 Req'd Qty: 4.00			Cust Item I Customer:	D:					albib 118 1781 1881
	Process Plan: MG QC:		Date: 0-3-16	Tooling: SPC (Y/N):	Date:			F		art	
Sequence ID/ Work Center ID		Operation Description	· <u></u>	Set Up/ Run Hours	Draw Number	Draw Rev.	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp.
Draw Nbr	Rev	ision Nbr			 -						
D4035	Α										
100 Large Fab Large Fab	-	2- Drill hol 3- remove i	minum rod Batch: MIN 86 O Min.os.i6 35-7as per dwg D4035 e using DT9563 and chamfer dentification marks and deby shing in rib and grind weld f	urr	;		 .		4	100	3.29

110

QC9- Inspect visual per QSI004- Fusion Welds

0.00

Memo

0.00

BE10-03-29

Quality Control

W/O:			W	ORK ORDER CHANG	ES					
DATE	STEP	PRO	OCEDURE CHA	ANGE	В	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector	
Part No	:	PAR #:	Fault Cate	egory:	NCR: `	es N	lo DQ	A:	_ Date: _	
	R	esolution:	Disposition	on:	_ QA: N/	C Clo	sed:		Date:	
NCR:			WORK ORD	ER NON-CONFORMA	NCE (I	ICR)				
DATE	STEP	Description of NC	Corrective Action		Section B		Verification		Approval	Approval
DAIL	SILF	Section A	Initial Chief Eng	Action Description Chief Eng		gn & Date	Secti		Chief Eng	QC Inspector
							 			-

Work Order ID 56977

Tuesday, March 16, 2010 10:20:59 AM



Page 2

Item ID:

D4035-047

Accept



Setup Start

Stop



Revision ID:

Item Name:

Lid Rib Assembly, Aft (Light)

Start Date:

3/16/2010

Start Qty: 4.00

Req'd Qty: 4.00



Cust Item ID:

Customer:

Reference:

Approvals:

Required Date: 3/23/2010

Process Plan:

Date:

Tooling:

Date:

Run Start

Stop

QC:

Date:

SPC (Y/N):

Date:

Reject

Insp.

Sequence ID/ Work Center ID

120

Quality Control

Operation Description

QC5- Inspect part completeness to step on W/O

Memo

Set Up/ **Run Hours** Draw Number Draw Plan Rev. Code

Accept Qty

Reject Qty

Number Stamp

Packaging

Packaging

130

Identify as per dwg & Stock Location:

Memo

0.00

0.00

140

QC

Quality Control

QC21- Final Inspection - Work Order Release

0.00

Memo

0.00

10/03/31 HJ

Dart	Aero	spa	ce	Ltd
------	------	-----	----	-----

W/O:			W	ORK ORDER CHANG	SES				
DATE	STEP	PROC	ANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector	
Part No	•	PAR #:	_ Fault Cat	egory:	_ NCR: Yes	No DQA	ı:	Date:	
		esolution:							
NCR:		W	ORK ORE	DER NON-CONFORM	ANCE (NCR)		- 11	
DATE	STED	Description of NC			Section B Verific			Approval	Approval
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section		Chief Eng	QC Inspector
									-
					ļ				
		;							
				·					
									i

Picklist Print

Tuesday, March 16, 2010 10:20:58 AM

Work Order ID: 56977

D4035-047

Parent Item Name:

Lid Rib Assembly, Aft (Light)

Comments:

Parent Item:

IPP RevA: new issue DD 10.01.25 verified by:EC

per dwg revA 10.03.15 verified by:EC

Start Date: 3/16/2010

Required Date: 3/23/2010

Start Qty: 4.00

Required Oty: 4.00

Component	Item	ID/
Item Name		
D4025 11		

Item ID

Replacement Mfg/ Purch Manufactured

Primary Bin Item Location No

Last Location

IPP Rev:B as

Route Seq ID 100

Unit of Measure Hand Each 0.0000

Remaining Oty on 8.0000

Qty Qty To Pick Issued

Date Issued

B56958--8 GC 10.03.29

Status



Bushing

M6061T6TS0.750W.06

Purchased

No

100

Loc Qty

f

270.4300 7.8947

Loc Code




Warehouse	
Location	

Location	
Main Warehouse	
MAT	270.43
103069	147.94
104422	69.75
16441	18.74
9671	34

Page 1


	Dart	Aerosp	ace Ltd
--	------	---------------	---------

	 -								
W/O:			WO	RK ORDER CHANG	BES				
DATE	STEP	PR	NGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector	
Part No		PAR #:							
	Res	solution:	Disposition	:	_ QA: N/C Cld	sed:		Date: _	
NCR:			WORK ORDE	R NON-CONFORM	ANCE (NCR)			· · · · · ·
DATE	STED	Description of NC	on of NC Corrective Action			Verific	rification Approval		Approval
DAIL	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section		Chief Eng	QC Inspector




Dart Aerospace L	.td
------------------	-----

	•								
W/O:		1000	WO	RK ORDER CHANGI	ES				
DATE STEP			OCEDURE CHAI	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector	
									:
Part No		PAR #:	Fault Cate	ory:	NCR: Yes	No DQA	\ :	Date: _	
	Reso	olution:	Disposition	:	QA: N/C Clo	sed:		Date:	
NCR:			WORK ORDE	R NON-CONFORMA	NCE (NCR))			
DATE	STEP	Description of NC			Section B Ve			Approval	Approval
DATE	SIEF	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section		Chief Eng	QC Inspector
 -									
	1								




Dart Aerospace Lt	d
-------------------	---

W/O:		WORK ORDER CHANGES										
DATE STEP		PRO	OCEDURE CHA	NGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector			
Part No	:	PAR #:	Fault Cate	gory:	NCR: Yes	No DQ	A:	Date:				
		solution:				Date:						
NCR:		,	WORK ORD	ER NON-CONFORM	MANCE (NCI	₹)		,				
DATE	STEP	Description of NC	1	ection B	Verific	cation	Approval	Approval				
<u> </u>		Section A	Initial Chief Eng	Action Description Chief Eng	n Sign o		ion C	Chief Eng	QC Inspector			
									-			
		e.										
		•										




Dart Aerospace Lte

W/O:		WORK ORDER CHANGES									
DATE STEP		PRO	OCEDURE CHAI	NGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector		
Part No	•	PAR #:	Fault Categ	gory:	_ NCR: Yes	No DQ	A:	_ Date: _			
					QA: N/C Closed: Date:						
NCR:			WORK ORDE	ER NON-CONFORMA	ANCE (NCF	l)					
DATE	STEP	Description of NC		on B	Verific		Approval	Approval			
	0,2,	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Secti	on C	Chief Eng	QC Inspector		
								i			
		100-100									



Dart Aerospace L	.td
------------------	-----

	•												
W/O:		WORK ORDER CHANGES											
DATE STEP		PRO	PROCEDURE CHANGE By			Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector				
·													
Part No	•	PAR #:	Fault Cate	gory:	NCR: Yes	No DQ	4 :	Date: _					
				QA: N/C Closed: Date:									
NCR:		,	WORK ORD	ER NON-CONFORMA	NCE (NCR)								
DATE	STEP	Description of NC		on B	Verific	ation	Approval	Approval					
	Section A		Initial Action Description Chief Eng Chief Eng		n Sign & S		on C Chief Eng		QC Inspector				



Dart	Aeros	pace	Ltd
------	--------------	------	-----

W/O:		WORK ORDER CHANGES										
DATE STEP		PRO	OCEDURE CH	ANGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector		
					***************************************				1 Tod Wigi			
										i		
							· · · · · · · · · · · · · · · · · · ·			***************************************		
Part No	:	PAR #:	Fault Cat	egory:	NC	R: Yes	No DQ	4 :	Date:			
		solution:										
NCR:				DER NON-CONFO				a				
DATE	STEP	Description of NC	Corrective Action Sec				Verific	ation	Approval	Approval		
DATE		Section A	Initial Chief Eng	Action Descrip	otion	Sign & Date	Secti		Chief Eng	QC Inspector		
										-		
					•							